10/22/2025 Vessel Auction			
Auction	Description	Winner	Winning Bid
51	Rib Assem Part # 186A1305-2		
	Splicest Part # 186A1230-2		
	RIBASSEM PART # 186A1307-3		
	Rib Assem Part# 186A1306-2		
	Rib Assem Part# 186A1304-1		
	Rib Assem Part# 186A1302-1		
	Splicest Part# 186A1230-1		
	Rib Assem Part # 186A1303-2		
	Rib Assy Part# 186A1304-2		
	"Ribayles Part# 186A1301-2		
52	"Helicopter Fitting Part# 412-010-111-103 for Bell 412 Helicopter Mfg.: Bell Textron"		
200	1991 25' Grady White Sailfish 25 Sport Bridge (No Trailer), HIN# NTLCV578C191, Reg# FL3857 HA 2025, Fiberglass, Deep-V Hull, PROPULSION: Yamaha 225 HP Twin Outboards, Port Mdl## LF225TXR, Port SN# has a damaged data plate with partial SN#10082?, Gas, 4-Stroke, Starboard SN# Damaged data plate with partial Mdl# LF225?, Partial SN# 100?, No Generator, NOTES: HIN# reported is not what can be confirmed as it is painted over and unreadable; Hull has scratches and dings, Damage on the stern in the bow to the fiberglass and gelcoat, Bottom anti-fouling paint looks new; Interior in poor condition; Outboards start and run, Hours of operation and maintenance history are unknown, Above information was derived from report dated March 2025	Cote, Alejandro [15]	$4,800.00
201	1997 27' Sea Ray 280 Sun Sport (No Trailer), HIN# SERT2147G797, FL 1132 KY, Fiberglass, Deep-V Hull, Propulsion: Mercury 225 HP Twin Outboards, Port Mdl# 225CXXLV, Port SN# 2B025735, Gas, Starboard Mdl# 225CXXLV, Starboard SN# 2B128025, No Generator, Notes: In overall poor shape; The hull has scratches and dings, There are several poorly done repairs to the hull at and below the waterline; Hull below the waterline is stained and has residual hard-growth from being in the water with no antifouling bottom paint; The vessel has been modified, It was build with inboard/outboards and were removed and a stern extension was added to now be powered by twin outboards; The outboards have cowlings that have "300" but these are only 225 HP; Both outboards are the same model so they both rotate in the same direction - not counter-rotating; Both outboards start and run; Hours of operation and maintenance history for the outboards are unknown; There are numerous holes/openings in the dash at the console from equipment that has been removed; The bimini top and the upholstery in the cockpit are in fair condition; Down below is in poor condition; Settee table is missing; Vinyl flooring is coming apart	strickland, III, James [81]	$11,250.00
202	2006 23' Sea Fox Walk-Around (No Trailer) "Grace", HIN# LYGHE184C606, Fiberglass, Deep-V Hull, PROPULSION: 2004 Mercury Single Outboard, 225 HP, Starts and Runs, Hours of operation and maintenance history are unknown; Gas, 4-Stroke, Mdl# 225XXLEFI, SN# OT962871, No Generator, Notes: Vessel is in fair condition; Hull has scratches and dings; Several places where the stainless steel fitting is bleeding rust; Cabin is in fair shape; No cushions and settee table is missing. Information above was derived from report dated February 2025		
203	2000 23' Boston Whaler 23 Outrage Center Console (No Trailer), HIN# BWCAK380J900, Fiberglass, Modified V-Hull, PROPULSION: Twin Yamaha Outboards, 200 HP, 2-Stroke Gas, Starts and runs; Hours of operation and maintenance history are unknown; Port Outboard Mdl# 200AET, Port SN# 1050223, Starboard Mdl# L200AET, Starboard SN# 1009616, No Generator, Notes: Hull has scratches, dings, needs detailing; Antifouling bottom paint needs to be re-applied; Damage to the rub-rail on the starboard side; Top-side gel-coat has rust stains; Upholstery is in fair condition; Large hole in the consol at the helm The information above was derived from report dated February 2025	SALAZAR, AGUSTIN [69]	$12,250.00
204	"2005 47' Tecnoyacht Motor Yacht (No Trailer), HIN Unknown - Buyer will be responsible for having a HIN put on the boat post sale, title paperwork will reflect HIN unknown, Reg# BVI 738683 Fiberglass, Modified V-Hull PROPULSION: Volvo Penta Twin Inboards, Diesel, Port Engine Mdl# D9575, Port SN# 70090106288 NOTES: This boat recently sank and is not sea-worthy, Hole in hull, Cannot be trailered, Exact model of this vessel is unknown, Cracks, gouges, scrapes, tears throughout, Several compartments are damaged, Termite damage Engines do not start or run, Hours of operation are unknown"	SALAZAR, AGUSTIN [69]	$550.00
205	"1986 26' Sea Ox (No Trailer), HIN# XNA60116F686, Reg# FL 3102 PM, Fiberglass, Deep-V Hull, No Generator, Notes: Exact model is unknown, In overall poor condition; Hull and topside have scratches and dings; Deck has soft spots; Hole in the dash from where electronics were removed; Wall coverings are dirty, broken door, No carpeting, Both outboards in poor condition and do not start; Steering system is very stiff; Paint is peeling off the lower units and the cowlings are in poor shape; Hours of operation and maintenance history are unknown. 200 HP Yamaha Outboard, Mdl# TXRR, Port SN# UL765226 200 HP Yamaha Outboard, Starboard Mdl# L250TXRR, Starboard SN# UL705201"		
	200 HP Yamaha Outboard, Starboard Mdl# L250TXRR, Starboard SN# UL705201		
300	Engine Parts: Yamaha Long Block Assembly - Model # 6AW-11000-02-00, On 2 Small Crates, 2 EA	MILLER, SHAUN [52]	$4,000.00
301	Boat Engine Part: Boat Engine Crank Shaft	strickland, III, James [81]	$916.00
	Boat Engine Part: Bottom Cowling Motor Tray		
	Boat Engine Part: Lower Unit For Boat Engine		
500	Mercury 350 HP Starboard SN# 2B656635	Crespo Dones, Pedro A. [12]	$4,200.00
	Mercury 350 HP Portside SN# 2B662239, Note: Engine covers are labeled 300 HP, Model and Serial Numbers are labeled 350 HP; The operational condition of the engines cannot be determined without an inspection by a		
502	115 HP Yamaha Outboard Motors, SN# 68WX800363 & 68VX701314		
503	300 HP Yamaha Outboard Engine, F300FST2, Gasoline, SN# 6Ka-U-1001819		
	Yamaha engine		

504	2003 15' Boston Whaler 150 Super Sport (No Trailer), HIN# BWCE0993I203-150SP-303, FRP (Fiber Reinforced Plastic), Reg# PR 4257 AB, PROPULSION: Yamaha 90 HP, Gasoline, SN# 6E5-X-732766-R, Notes: Needs FRP, electrical and cosmetic repairs; Poor maintenance and electrical condition; The vessels deck is in poor structural condition, Main engine bed is located at the ransom of the vessels, Information above derived from report dated March 2025	Crespo Dones, Pedro A. [12]	$7,250.00
505	2001 22' (LOA) Pro Sports 22 Center Console (No Trailer), (2) 115 HP Yamaha Outboard Motors, SN# 68WX800363 & 68VX701314	Pomales, Xavier [26]	$11,000.00
600	2021 11' Sea-Doo pw gtx 230, 325 3-Person PWC (No Trailer), No Trailer HIN# YDV83612E121 (updated), Propulsion: Bombardier Inboard Jet, Gas, Inboard, 4-Stroke, Fuel Injected Mdl# PW GTX 230, SN# Unknown, Year updated to 2021 (was 2024) HIN Updated Minor scrapes and scratches on the topsides, one gouge on the portside aft Bottom of the vessel has some scrapes from beaching Plastic nose piece is broken off Seating is dirty and stained but in good condition Plastic top to the engine compartment partially under the seating is loose, screws have been removed, plastic cap is missing Engine does not start, hours of operation and maintenance history are unknown	Laguna, Benjamin [9]	$1,150.00
602	1983 Sea Ray Cuddy Cabin (No Trailer), HIN# SER038M10683, Reg# CF 2517VJ		
603	"1990 25' Sea Ray Walkaround (No Trailer), HIN#: SERC3820K990, Reg# CF 3820 ND 2025 Fiberglass, Deep-V Hull PROPULSION: Mercury 25' Twin Outboards, Gas 135 HP, 2-Stroke, Mdl: Blackmax NOTES: Bottom and sides are in poor shape with scratches, scuffs and chips Bottom is stained from years of being in the water with no anti-fouling paint Small repair on the bow around the tow eye Gelcoat has scratches and chips Deck forward and the gunnel in the cockpit have bad spider-cracking in the gelcoat Aft in the cockpit has a section that has been cut-out and hatch is missing Top of dash is sun damaged and faded Aluminum frame for the top and the windshield have light pitting from long term corrosion issues; Windlass is rusted Twin outboards turn over but do not start Cowlings have been painted black and the data plates have been removed Above info derived from report dated June 2025"		
604	1977 21' Sea Ray (No Trailer) HIN# SER1048A1177, Reg# CF4702ZD		
700	1999 26' Monterey 262 Cruiser (No Trailer), HIN# RGFN0151K899, Reg# CF7811ZJ, Fiberglass, Deep-V Hull, PROPULSION: Yamaha Twin 300 HP, 4-Stroke, Outboards, Gas, Port SN# LF300XCB, Port SN# 2076335, Starboard Mdl# F300VCA, Starboard SN# 076335, NOTES: The vessel has been modified and the single inboard/outboard has been removed, Stern extension has been added to install twin outboards for power. This is not the way the boat was designed to operate and the quality of the installation has not been investigated; Hull and topsides have scratches and dings; Cabinet doors are broken off, Head door has been removed, Microwave has been removed; Thru-hull valves in what was the engine compartment are closed and secured; No battery charger onboard; Port outboard is stuck in down position with trim/tilt motor issues and there is heavy growth on the lower unit. The hours of operation and the history of maintenance are unknown; The Hin# matches this vessel but the documentation numbers 1151460 (Official Number) in what was the engine compartment does not match this vessel and comes up with a different HIN for a 2002 vessel out of Florida.	Leon, Eduardo [84]	$1,100.00
701	"1973 29' Pacemaker (No Trailer), ""No Mas Pesos"" HIN: Unknown (Buyer responsible for having a new HIN put on the boat as part of registereing it), Reg# CF 9557 EV 2023, Fiberglass, Modified V-Hull Twin Inboards, (possibly Crusader), Gas, 8-cylinder Port Engines: 338.9 hours, Starboard hours: 373.2 hours, The engine hours are very low for a vessel this age and be unreliable Generator, In overall poor condition Cabin has signs of termites, The above information was derived from report dated April 2025"		
800	1990 22' Bayliner Trophy (No Trailer), HIN# BL5A26FTF990, Reg# CF8080NB, PROPULSION: No Engine; , No Generator, Notes: Hull and topsides have scratches and dings, but are in fair shape overagell; Topsides and cockpit are in fair shape; Bait taknk in the cockpit; Hardtop in fair condition; Door and hatch for the cabin are in fair condition; Settee table is missing Above information was derived from report dated February 2025		
801	1997 28' Bayliner Walkaround (No Trailer), HIN# USDA03FHK697, Reg# CF 9801 PD, Fiberglass, Modified-V Hull, PROPULSION: 2012 350 HP Yamaha Single Outboard Engine, SN# 1004558, 4-Stroke, Notes: The lower unit is not original, The skeg has a chunk out of it; No keys to the outboard; Engine hours of operation and maintenance history are unknown; The vessel looks like it was originally powered by twin outboards and has been repowered to just a single 350 HP Outboard engine; Everything on the dash has been removed except for the fuel gauge; There are 2 large holes in the dash where electronics have been removed; The original twin controls are in place and have been modified down to a single control; Down below is in fair shape; Microwave has been removed; Eisenglass enclosure is in fair shape; Metals have light corrosion issues, Above information derived from report dated May 2024		
802	"1992 20' Sea Ray 200 Cuddy Cabin (No Trailer), HIN #: SERV5894D292 No Trailer Reg# CF 4838VT, Gasoline Damaged throughout"		