5.20.25 Vessel/Aircraft Auction			
Auction	**Description**	**Winner**	**Winning Bid**
100	Aircraft Battery Packs	TAPS AERO	$2,100.00
101	Blade, LPT STG 4 PART # 338-108-504-0, Mfg: CFM International	Gutierrez, Hernando [102]	$9,750.00
102	AIRBUS INLET COWL PART # 642-1000-505.	QUALITY AEROPARTS, INC	$62,000.00
103	Bearing, Trunnion – Spar 3 Aircraft Parts, Part # ABC48G-302	TAPS AERO	$1,000.00
104	Aircraft Parts - Undercarriage Assembly		
200	1989 Sea Ray 380 Aft Cabin (No Trailer) HIN# SERF1523A989, Reg# FL 5571 ND, FRP (Fiber Reinforced Plastic), Modified-V Hull, PROPULSION: Volvo Penta Twin, L-6, Turbo Aftercooled, Port Mdl# TAMD61A, Starboard Mdl# TAMD61A, SN#: N/A, Engine Hours of Operation: Unknown, Transmission Manufacture: ZF, Port Transmission Mdl# IRM220A, Starboard Transmission Mdl# IRM220A, Starboard Transmission SN#: 220.1991, Generator Manufacturer: Northern Lights, Generator Mdl/SN# N/A, Generator Hours of Operation: 7,159.3 hours at analog hour meter, Diesel, Interior Appointments: (2) Staterooms, (2) Berths, (2) Heads, Vizio LCD TV, Insignia LCD TV, Orion TV/DVD, Etec CD/DVD Player, GALLEY/APPLIANCES: Refrigerator/Freezer, Cooktop, Compact Oven, Microwave, NOTES: This vessel did not appear to be operation at time of this report. Signs of exhaust leakage noted throughout the engine room (including exhaust soot), Machinery throughout the engine room exhibited excessive corrosion and signs of neglect, The engine room bilge was found to be soled with standing water and oil, Standing water was sighted in the forward bilge, A section of the stainless steel safety railing was missing (port side), Damages were sighted throughout the rub-rail, FRP/get-coat damages throughout the hullsides, main deck and bilges, Various cosmetic and/or structural deficiencies throughout due to general lack of maintenance or care, As reported September 2023		
300	1980 32' Chris Craft 313SL Scorpion "Reel Wet", (No Trailer), HIN# CCBAJ031M80J, State Reg# FL 3702 CW, FRP (Fiber Reinforced Plastic), Deep-V Hull, PROPULSION: Twin 2020 Mercury Marine Twin, 4-Stroke Verado Outboards, Port Mdl# 1400030A/400CXXL, Starboard Mdl# 1400029A/400XXL, Port SN# 2B707482, Starboard SN# 2B659820, Gasoline, NOTES: Decals on the outboard motor cowlings indicated that the motors were Mercury Racing 400 HP outboard motors, but the ID tags indicated that the motors were actually Mercury Verado 400 HP outboard motors, Main cabin entry door is missing, Fabric wllcovers are missing in the main cabin interior, GPS/Navigation system has been removed, FRP/gel coat damages throughout the hullsides, main deck and bilges, Various cosmetic and/or structural deficiencies dur to general lack of maintenance or care. When this boar was manufactured in the 1980, the specifications published by CHris-Craft stated a maximum HP of 500 HP for this boat. This boat is currently outfitted with (2) 400 HP Mercury outboard motors. In surpassing the stated maximum horsepower limitation for this transom, the stability and structural integrity of this vessel is called into question	United boats and parts liquidators	$30,000.00
301	2002 30' Wellcraft Coastal (No Trailer), HIN: WELHHA09G102, Reg: FL 2962 TP 2024, PROPULSION: Mercury Marine Twin Outboards, Port Outboard: 300CXL 300-HP, 4-Stroke, Year Ukn, Port Outboard Mdl# 13000060A, Port SN# 3B011486, Starboard Outboard: 300-XL 300-HP, 4-stroke, Year Unk, Starboard Outboard Mdl# 13000052A, Outboard SN# 3B011913, NOTES: The model of this Wellcraft should be the 290 which measures 30' but cannot be confirmed, Hull gelcoat is sun-damaged and yellowing with scratches, gouges and dings, Hull below the waterline has numerous gouges and scrapes that appear to be in to the fiberglass, Outboards have corrosion on the lower units around where the mounting bolts attach the outboards to the hull, Port outboard has a key and runs, Starboard outboard does not have a key, Year of manufacture, hours of operation and maintenance history are unknown. As reported September 2024		
302	1990 26' Pursuit 2650 Walkaround, CZECH MATE", (No Trailer), HIN: SSUB6059J990, FL Reg: 8697 FH Deep-V, Fiberglass, PROPULSION: 2007 Yamaha Twin Outboards, Mdl#: LF250TUR 4-stroke, Port SN# 1010375, Starboard Mdl# F250TUR, 4-Stroke, Starboard SN# 1020305, No Generator, NOTES: Stern extension for the outboards is separating from the hull; Hull and topsides have scratches, scraps and dings, Gelcoat needs detailing, Large hole in the dash from missing electronics, Down below is striped and bare, Hard-top is in good shape, Twin outboards started and ran, Hours of operation and maintenance are unknown	Hialeah finest	$7,750.00
303	Triple Axle Trailer, EEZZZZ-On Inc., VIN# 1ZIBA24244M024067, License Plate: 0901AU, Aluminum, Notes: One of the wheels (tire, hub, bearing, entire assembly) is missing on the driver's side		
400	"2005 22' Progression 22 (No Trailer) High Performance 2005 HIN# PG122108H405 FRP (Fiber Reinforced Plastic) Reg# NY1036 MC PROPULSION: 2007 300 HP Mercury 300XS, Salt water cooling, 6-cylinders, Gasoline Operational condition unknown. Notes: In good structural condition and fair electrical and cosmetic condition. As reported Dec 2023"		
401	2016 22' Yola Spider 22 Open CC, (No Trailer), HIN# FMB00001J616, State Reg# PR 9116 BB, Note: The HIN includes Luquillo Boat Glass Inc at MIC, PROPULSION: (2) 115 HP Yamaha F115BET, Port SN# 6EK-L-1122719, Starboard SN# 6EK-L-1123408, As reported March 2025	Colon, Felix [12]	$29,000.00
402	Yamaha 90, Mdl# F901B	torres, wilson [51]	$1,750.00
500	200 HP Yamaha Outboard Motors Case	De Jesus, Gabriel [72]	$21,000.00
	200 HP Yamaha Outboard Motors Case		
501	40 HP Mercury Outboard Motor SN# ON452880	Rosado, Jairo [57]	$600.00
502	40 HP Mercury Outboard Motor, SN# ON452873	Rosado, Jairo [57]	$1,550.00
	40 HP Mercury Outboard Motor, SN# ON452868		
503	75 HP Yamaha Enduro Outboard Engine, Mdl# E75MMHD, Gasoline, SN# 692-L-1077250-A	torres, wilson [51]	$650.00
504	75 HP Enduro Yamaha Outboard Motor (No SN#)	torres, wilson [51]	$891.00
506	(2) 250 HP Yamaha Outboard Engines	Lopez, Fernando [7]	$1,050.00
507	"(2) 90 HP Suzuki DF90A Engines "	torres, wilson [51]	$3,300.00
508	40 HP Marlin Outboard Motor SN# IALGEGD0163	Lopez, Fernando [7]	$550.00
601	2007 25' Bayliner Trophy Pro (No Trailer), HIN# THMA12FXG607, Reg: CF 5380TB (2024 CA), Some damage around hull, gunwales, deck and inside cabin, PROPULSION: (2) Yamaha 150 HP Outboard Engines,	Cesena, Carlos [45]	$7,500.00
602	1999 25' Proline 241, (No Trailer) HIN# PLCWF122D999, Reg# CF9201PT, PROPULSION: (2) Yamaha 300 HP 4-Stroke and 15 HP 4-Stroke Outboard Engines, Gasoline, Poor condition throughout	Dynacore	$4,400.00

603	1990 24' Starfire Fisherman 245 Hardtop (No Trailer), FRP (Fiberglass), Deep-V Hull, HIN# SRFF4079E990, Reg# CF 8799 UE, PROPULSION: Mercruiser, Volvo Penta Outdrive, Data plate has been removed, Single Pro Outdrive, 6-cylinder Gas, Inboard, Year Unknown, Damaged throughout, Notes: Hull has multiple deep scratches, gouges, areas of wear, Hull has a water leak, Topsides and hardtop in poor condition, As reported June 2024		
604	"1993 19' Wellcraft (No Trailer) HIN# WELA886YK293, Poor Condition"		
605	1985 22' Bayliner Cuddy Cabin (No Trailer), HIN# BLBA19SJF485, Reg CF 1334 HJ 2023, PROPULSION: Volvo Penta Single Inboard/Outboard, Gas, Non -operational, poor condition, This vessel is in overall poor condition, Reported October 2024		
606	1994 22' Bluewater Cuddy (No Trailer), HIN# BWY1E0656394, Reg: CA 2024/CF 9070NL, Gasoline, No keys, Very poor condition, Vessel leaks, PROPULSION: Yamaha 115 HP 2-Stroke, Engines run roughly, Decks are rotted and soft	Skelton, Dennis [23]	$100.00
607	2000 Wellcraft 22 Walkaround (No Trailer), HIN# WELHJA49H900, Reg: CF 4689 ZF 2025, Fiberglass, Deep-V Hull, PROPULSION: Yamaha Single Outboard Motor, Outboard Mdl# F225TXRB, SN# 1004885, Gasoline, 225 HP, 4-Stroke 12/2002, No Generator, Notes: Hull and bottom has scrapes, gouges and damage to the gelcoat/fiberglass, Vinyl name and graphic near the stern on the sides is scratched, Gelcoat is spider cracking, Rub-rail is damaged, Bimini top in poor condition, In the cockpit, the added rubber deck is peeling and in poor shape, Deck is stained, Interior in poor shape and damaged, In March of 2025, the outboard engine started and ran, Maintenance history is unknown, Cowling is scratched , Lower unit has broken fin, As reported April 2025	Davenport, Scott [13]	$4,000.00
608	"1983 Sea Ray Cuddy Cabin (No Trailer) HIN# SER038M10683 Reg# CF 2517VJ 2025"		
609	2005 Sea-Doo / BRP RXT, HIN# YDV30779C505	Whitcomb, Mark [88]	$1,200.00
610	2017 10' Yamaha EX Deluxe Jet Ski (No Trailer), HIN Removed, State Reg#: Damaged and unreadable 2023, PROPULSION: Yamaha Marine, Gasoline Jet Pump, 3 cylinder, 4-Stroke, Model and SN# unknown, No Generator, Poor condition; Buyer responsible for having new HIN put on watercraft; As reported February 2025	Templar enterprise	$275.00
650	"2000 23' Bayliner Trophy Walk-Around (No Trailer) HIN# BLWA21FPK900 Reg# FL 3199 RN 2025 Fiberglass Deep-V Hull PROPULSION: Yamaha 200 HP Single Outboard, 2-Stroke, Gas Reg# CF 3199 RN NOTES: Hull and topsides have dings, scratches, stained and needs detailing, no damage reported Upholstery is sun-damaged No Keys Model, Hours of operation, Manufacture year and maintenance history are unknown GPS monitor on the dash at the helm is damaged and not useable Settee table is missing As reported February 2025"	Skelton, Dennis [23]	$2,600.00
651	2000 33' Fountain 5-0 CF8213 VF (No Trailer), HIN# 3FGQ9X009, Has keys PROPULSION: (2)Yamaha 250, 4-Stroke Outboard Engines(I engine is operational), Notes: Broken Stern light, Numerous holes from missing items, Broken Hatches, Trim pump leaks	Tevay Management LLC	$4,600.00
700	20' Sea Ray 200 Cuddy Cabin (No Trailer), Reg# CF 4838VT, Gasoline, Damaged throughout. HIN SERV5894D292		
701	"1982 31' Wellcraft (No Trailer), Model unknown Appears to have modified topsides Aft deck is stripped bare with no seats or tables There is a tank that has been added on the aft deck Gelcoat on the hull and topsides has scratches, gouges and needs wax Corrosion and rust issues in multiple areas Access cover is missing under the steering wheel Trim in the cockpit is in poor shape Large hole in the cabinet where refrigerator was removed PROPULSION: Twin Gas inboard/outboards that do not start and are in poor shape Engine compartment is very dirty and oily, indicating oil leaks during operation Hours of operation and maintenance history unknown Information derived from report dated February 2025" HIN WELA9340M82G		