8/20/25 Vessel/Aircraft Auction			
Auction	**Description**	**Winner**	**Winning Bid**
100	"Aircraft Tires & Rubber Seals, Good Year Aircraft Tires 12 qty. 22x6.75-10 Part# 265K Michelin Aircraft Tires 6 qty. 26x6 6R14 Part# M15101-01 Rubber Seals Part# BT337-1 10 qty. " rubber seals part bt337-1 aircraft tires part m15101-01	Laredo Aviation Sales and Leasing	$4,064.00
200	1995 30' Grady-White Marlin 300 Walkaround, HIN# NTLEA135L495, Reg# FL 8371 JM, Fiberglass, Deep-V Hull, PROPULSION: 2006 Yamaha 250 HP, 4-Stroke Twin Outboards, Port SN# 1004705, Port Outboard Type: LF250TXR, Port SN# 1004705, Starboard Type: F250TXR, Starboard SN# 1015635; Notes: Fiberglass and rub-rail on the starboard side are damaged where it is attached to the boat; Starboard side of transom has a crack; Down below is in poor condition; Yamaha outboards are in good condition and start and run. Hours of operation and maintenance history are unknown. Information was derived from report dated September 2024	Major Oak Builders & Consultants, LLC	$18,250.00
201	"2002 30' Wellcraft Coastal (No Trailer) HIN: WELHHA09G102 Reg: FL 2962 TP 2024 PROPULSION: Mercury Marine Twin Outboards, Port Outboard: 300CXL 300-HP, 4-Stroke, Year Ukn Port Outboard Mdl# 13000060A, Port SN# 3B011486, Starboard Outboard: Year Unk, Starboard Outboard Mdl# 13000052A, Outboard SN# 3B011913 NOTES: The model of this Wellcraft should be the 290 which measures 30' but cannot be confirmed Hull gelcoat is sun-damaged and yellowing with scratches, gouges and dings, Hull below the waterline has numerous gouges and scrapes that appear to be into the fiberglass; Outboards have corrosion on the lower units around where the mounting bolts attach the outboards to the hull; Port outboard has a key and runs, Starboard outboard does not have a key; Year of manufacture, hours of operation and maintenance history are unknown. As reported September 2024"	Hialeah finest	$18,250.00
202	"1998 27' Cobia Walk-around (No Trailer) HIN: CBA023WWB898 Reg# FL 2675 KD Fiberglass Deep-V Hull PROPULSION: Yamaha 225 HP 2-Stroke Outboards Port Outboard Hours of Operation: 429 Starboard Hours of Operation: 429 No Generator NOTES: Engines start and run, Maintenance and year of manufacture are unknown Hull and topsides need detailing, minor scratches and dings, damage to the port side rub-rail amidships Navigation lights are non-operation Bilge system is non-operation"	United boats and parts liquidators	$6,250.00
203	"1986 26' Pursuit 2600 Cuddy Cabin (No Trailer) HIN: SSUF6100B686 Reg# FL 4262 TA Deep-V Hull PROPULSION: 2017 Yamaha Twin Outboards, 250 HP, 4-Stroke Port Outboard Mdl# FL250HET, SN# 1003125 Starboard Outboard Mdl# F250HET, SN# 1007773 No Generator NOTES: Topsides and hull gelcoat have minor scratches & dings Bottom anti-fouling paint is in poor condition Hole in the dash from the chart plotter being removed Wall coverings and cushions are stained and dirty Refer is missing Outboards start and run, Port outboard is missing the zinc, Hours of operation and maintenance info are unknown. Information above derived from report dated December 2024"	Bullet Motorsports Inc	$6,250.00
300	Dinghy, Outboard: Tohatsu 40 HP/29.4 KW, SN# 070500BA, Mdl# MFS40A 2021 "2001 60' ft Sunseeker Yacht w/ Dinghy (No Trailer) Case #: 2024520100047401-001-0000-CS Case #: 2024520100047401-002-0000-CS Preview Details No Trailer Hull# XSK0153A101 HIN: Not readable (under the swim step) Reg: FL 9305 RW Hailing Port: Unknown Fiberglass Deep-V Hull 13' Dinghy (line item 002), No HIN on the Dinghy (Title transfer paper will show that HIN is ""unknown for the dinghy. Buyer responsible for obtaining new HIN for dinghy as needed to register it) Generator Type/SN# 20 kw Northern Lights; does not start, possibly from battery issue with the boat PROPULSION: MAN-Marine Diesel Twin Inboard Diesels Port SN#: Unreadable, Plate is painted over Port Engine Type/Year of Manufacture: 8v Twin Turbo Aftercooled Year Unknown, Transmission Mdl#: ZF3501V Direct Drive, SN# 20013322/20013323 Dingy Outboard: Tohatsu 40 HP/29.4 KW, SN# 070500BA, Mdl# MFS40A 2021 Battery issue with this vessel and the engine would not start for evaluation OTHER DETAILS: Retractable sunroof had to be manually closed, Tere was not enough battery power to close, Hull is blue/white and is sun-damaged White gelcoat is faded and yellowed, The blue gelcoat is very faded which is common for the blue color, gelcoat overall looks dirty, stained, and needs to be waxed, Multiple scratches and chips, Upholstery is in poor condition with sun-damage and tears Teak decks are in poor condition and need to be re-done, Wood table on the aft deck is stained and in poor shape and needs to be refinished Carpet dirty and in poor shape Wall coverings are dirty and are falling down 13' Tender appears to be in good shape and is powered by a Tohatsu 40 HP outboard that starts and runs and should be a 4-stroke Maintenance history of the outboard is unknown, Make of the tender is unknown Above information derived from report dated August 2024."	redstar, sarah [59]	$48,000.00

301	"1979 42' Post Marine Sportfisher (No Trailer) ""Easy Time"" HIN PMC42143N79K Reg# FL 1890 TW Fiberglass Modified V-Hull PROPULSION: Cummins Twin Inboard Diesels Port Mdl: 6CTA, Port SN# 83N Starboard Mdl# 6CTA 83N Generator: Phasor, Unknown model and size Auxiliary Outboard: For Tender, Mercury Outboard, Unknown HP and Model NOTES: Vessel is in fair to poor condition Wood areas have termite issues Inboard diesels start and run, Hours of operation and maintenance history are unknown Generator starts and runs, Hours of operation and maintenance history are unknown Above information was derived from report dated November 2024"	Northwest Auto Group	$1,200.00
302	"1989 38' Sea Ray 380 Aft Cabin (No Trailer) HIN: SERF1523A989 Reg# FL 5571 ND FRP (Fiber Reinforced Plastic) Modified-V Hull, LOA is 42' 7"", PROPULSION: Volvo Penta Twin, L-6, Turbo Aftercooled Port Mdl# TAMD61A, Starboard Mdl# TAMD61A SN#'s - N/A Engine Hours: Unknown Port Trans Mdl # IRM220A, Starboard Trans Mdl# IRM220A, Starboard Trans SN# 220.1991 Generator: Northern Lights, 7,159.3 hours at analog hour meter Diesel INTERIOR APPOINTMENTS: (2) Staterooms, (2) Berths, (2) Heads Vizio LCD TV Insignia LCD TV Orion TV/DVD Etec CD/DVD PLAYER GALLEY/APPLIANCES: Princess 3-Burner Electric Cooktop Little Litton Compact Oven Amana Radarange Plus Microwave NOTES: Non operational Exhaust leakage, throughout the engine room Machinery has excessive corrosion Standing water and oil in engine room bilge, Stading water in forward bilge Stainless steel safety railing portion is missing Rub-rail damages FRP/gel-coat damages throughout hullsides, main deck and bilges Various cosmetic and/or structural deficiencies due to general lack of maintenance or care Various characters of the HIN# were illegible, Above information was derived from report dated September 2023"	D.J.M BOOKS	$1,000.00
303	1985 36' Bertram, HIN# BERT0157G485, Model Unknown, Fiberglass, Deep-V Hull, PROPULSION: Detroit Diesel Twin Inboards, SN & Year are unknown, Notes: Inboard diesel engines do not run; Bow railing forward on the starboard side is damaged with portions missing; Door to the cabin is damaged; Super structure is in fair condition with no damage; Hull is in fair condition with no damage; Condition of hull below the waterline, props, shafts, rudders and zincs is unknown. Information derived from report dated August 2024	D.J.M BOOKS	$100.00
400	2000 Luhrs 37"2000 Luhrs 37' 400 Tournament Open Sportfisher (No Trailer) ""Drop N Bonds"" HIN# LHRLP207A000 Reg: FL 6819 TF FRP (Fiber Reinforced Plastic) Modified V PROPULSION: Cummins Marine Twin L-6, Turbo Aftercooled Port Mdl# 6CTA8.3-M, Port SN# 45900910 Starboard Mdl# 6CTA8.3-M, Starboard SN# 45912973 Engines Hours of Operation: Unknown Fuel Type: Diesel Generator: Kohler, Mdl# 8EOZ, SN# 0654364, Generator Hours of Operation: 2,582.8 hours at analog hour meter EQUIPMENT: VHF INTERIOR APPOINTMENTS: (1) Staterooms, (3) Berths, (1) Head AM/FM Radio & Media Plater GALLEY/APPLIANCES: Compact Refrigerator Compact Freezer Cooktop Microwave NOTES: Vessel is non-operational Port and starboard main engines are non-operational Machinery throughout the engine room has excessive corrosion and signs of neglect The HIN was not legible at the transom (covered by a decorative vinyl wrap) The HIN needs to be re-inscribed as per the Code of Federal Regulations. This boat is in overall poor condition."foot Sportfisher No Trailer Included	Knafo, David [76]	$3,100.00
500	300 HP Yamaha Outboard Engine		
501	90 HP Yamaha Outboard Engines	torres, wilson [17]	$7,750.00
502	200 HP Suzuki Outboard, SN# 20002F-340402	Rosado, Jairo [67]	$14,250.00
	200 HP Suzuki Outboard Motor, SN# 20002Z-340108	Rosado, Jairo [67]	$700.00
503	40 HP Mercury Outboard Motor	Bernaola, Rafael [62]	$600.00
504	150 HP Yamaha Outboard Engine, SN# 6G9X1004300, Gasoline	Marrero, Juan [71]	$550.00
505	115 HP Yamaha Outboard Motor	Rosado, Jairo [67]	$700.00
506	"115 HP Yamaha Enduro Outboard Motor SN# 10151"	Lopez, Fernando [31]	$325.00
507	40 HP Yamaha Enduro Outboard Motor (No Serial Number)	Rosado, Jairo [67]	$475.00
508	20 HP Mercury Outboard Motor	Barber, Joseph [2]	$1,250.00
600	"1971 44' Pacifica 44 Convertible Sportfisher (No Trailer), ""Banteng"", No HIN, Reg# CF 3685 SY Fiberglass, Modified-V Hull PROPULSION: Twin inboards (Mfg unknown), Diesel No Generator NOTES: No keys, Cap rail is missing wood plugs covering the screws; Areas on the foredeck around the window frames has gelcoat worn through to the fiberglass; Top to the bait tank is missing; Numerous cabinet doors missing; Main entry doors to the salon are missing; Decks are soft; Numerous holes where items have been removed; Various damage throughout, The 1971 model is not confirmed Information above derived from Report dated June 2025"		

601	1980 40' Viking Sedan Sportfisherman, HIN# VKY35751M80A, Fiberglass Modified Deep-V Hull, Back decking soft and in poor condition, One of the support stringers is missing, Flybridge deck is soft, Bow area is soft, Hull paint is chalky and faded with gouges scrapes and dings, Wood rub-rail paint is peeling, Plastic vents are sun-damaged and broken, Paint in poor condition, Cabin hatch forward is sun-damaged fiberglass mat is showing Wood trim in poor condition, Ladder to the flybridge has broken steps, Interior has exposed wiring Salon is striped with no furniture Bunks are missing mattresses, Flybridge enclosure in fair condition Bridge helm in fair condition, Operation of the controls has not been evaluated, Twin diesel engines do not start, gear below the waterline has not been inspected therefore operation and condition are unknown.		
602	"1973 29' Pacemaker (No Trailer), ""No Mas Pesos"" HIN: Unknown, Reg# CF 9557 EV 2023 Fiberglass, Modified V-Hull, PROPULSION: Twin Inboards, (possibly Crusader), Gas, 8-cylinder, Port Engines: 338.9 hours, Starboard hours: 373.2 hours, The engine hours are very low for a vessel this age and may be unreliable, No Generator, In overall poor condition, Cabin has signs of termites.Notes: HIN has been removed/painted over so the exact model of this vessel is unknown; Hull has scratches and dings; Paint is peeling on the wood trim, There are missing doors and damaged hatches, Wood swim-step aft has damage; In the flybridge, the space under the console is open and has exposed wiring, Wind-screen is sun-damaged; Twin inboard engines are in poor condition, Port engine starts, starboard does not start, The above information was derived from Report dated April 2025"		
700	"1998 27' Pro-Line 2610 Walkaround, No Trailer, ""Mama's Boys & Girls"", HIN: PLCWW037J798, Reg: CF 8885 RA 2025 LOA: 26', Fiberglass, , Deep-V Hull, Evinrude/BRP Bombardier Recreational Products, Twin Gas Outboards Port Year: 2012, Port Mdl# E200HCXAAC, SN# 5364484, Gas, 200 HP E-TEC 2-Stroke Starboard Outboard Year: 2013, Mdl# E200DHXAAD, SN# 5387020, Gas 200 HP, E-TEC, 2-Stroke Outboards start and run, Cowlings have minor damage, Hours of operation and maintenance history are unknown, No Generator, Vessel is in overall poor condition."	Evans, Austin [57]	$1,550.00
701	"2004 19' Bayliner (No Trailer) HIN# USHA05CNE304 Reg# CA CF2625RC Gas No Electronics on board"		
702	"1990 24' Starfire Fisherman 245 Hardtop (No Trailer) HIN# SRFF4079E990, Reg# CF 8799 UE, FRP (Fiberglass), Deep-V Hull PROPULSION: Mercruiser, Volvo Penta Outdrive, Data plate has been removed, Single Pro Outdrive, 6-cylinder Gas, Inboard, Year Unknown, Damaged throughout NOTES: Hull has multiple deep scratches, gouges, areas of wear, Hull has a water leak, Topsides and hardtop in poor condition Information derived from Report dated June 2024"		
703	2004 23' Trophy Pro 2302 Walk-Around, HIN# THMA49FPD404, Reg# CF 7416 RG, Fiberglass, Deep-V Hull, PROPULSION: 2004 Mercury Single Outboard, Mdl# 225XL EFI, SN# OT962791, Gasoline, 225HP, 2-Stroke, Does not run, Notes: Vessel in overall poor condition; Hull and bottom have scratches, dings, gouges into the fiberglass; Bow has damage around the tow ring which was poorly repaired; Rub-rail is damaged; Outboard does not start; Hydraulic steering does not work; Cockpit gelcoat is scratched; Plastic parts are sun-damaged and broken; Upholstery is sundamaged and in poor condition; Dash has a large hole from missing electronics; Window frames are corroded; Anchor chain is rusty; Plexiglass top for the entrance to the cabin is broken; Carpets and wallcoverings are stained, Table is missing. Information derived from report dated May 2025	zhdanov, Jordan [86]	$550.00
704	"1993 19' Wellcraft (No Trailer) HIN# WELA886YK293, Poor condition"		
705	"1983 Sea Ray Cuddy Cabin (No Trailer) HIN# SER038M10683, Reg# CF 2517VJ"		
706	"1990 25' Sea Ray Walkaround (No Trailer), HIN: SERC3820K990 Reg# CF 3820 ND 2025, Fiberglass, Deep-V Hull PROPULSION: Mercury 25' Twin Outboards, Gas 135 HP, 2-Stroke, Mdl: Blackmax NOTES: Bottom and sides are in poor shape with scratches, scuffs and chips; Bottom is stained from years of being in the water with no anti-fouling paint; Small repair noted on the bow around the tow eye; Gelcoat has scratches and chips; Deck forward and the gunnel in the cockpit have bad spider-cracking in the gelcoat; Aft in the cockpit has a section that has been cut-out and hatch is missing; Top of dash is sun damaged and faded; Aluminum frame for the top and the windshield have light pitting from long term corrosion issues; Windlass is rusted; Twin outboards turn over but do not start; Cowlings have been painted black and the data plates have been removed Above info derived from Report dated June 2025"		
800	"32' Wellcraft St. Tropez 3200 (No Trailer) HIN: WELC1285F586 PROPULSION: Twin gas Inboards in good condition, No keys, Generator does not run Hours of operation for Engines and Generator are unknown Information derived from Report dated Oct. 2022"	Hochman, Hoyt [88]	$1,100.00
801	"20' Sea Ray 200 Cuddy Cabin (No Trailer), HIN #: SERV5894D292, Reg# CF 4838VT, Gasoline, Damaged throughout"		