1/28/26 Specialty Auction			
Auction	**Description**	**Winner**	**Winning Bid**
100	RIBAYLES PART # 186A1301-2 RIB ASSY PART # 186A1304-2 RIBASSEM PART # 186A1303-2 SPLICEST PART # 186A1230-1 RIBASSEM PART # 186A1302-1 RIBASSEM PART # 186A1304-1 RIBASSEM PART # 186A1306-2 RIBASSEM PART # 186A1307-3 SPLICEST PART # 186A1230-2 RIBASSEM PART # 186A1305-2	Mola, Gustavo [1108]	$2,200.00
101	Fitting Part # 412-010-111-103 for Bell 412 Helicopter, Mfg.: Bell Textron	Hanson, Maddie [1109]	$4,100.00
203	1985 36' Bertram (No Trailer), Model Unknown, BERT0157G485, Fiberglass, Deep-V Hull, PROPULSION: Detroit Diesel Twin Outboards, 8-cylinder single turbo, NOTES: Inboard engines do not run, Port engine head removed; Bow railing forward on the starboard side is damaged with portions of it missing; Door to the cabin is damaged; Super structure is in fair condition with no damage; Hull is in fair condition with no damage, Information above was derived from report dated August 2024	Lackey, Fred [87]	$125.00
301	"1987 25' Chris Craft 254 Sea Hawk Walkaround (No Trailer) HIN# CCBBD114H687 Reg# FL 5003 FV 29' LOA Fiberglass/FRP (Fiber Reinforced Plastic) Modified-V Hull Propulsion 2023 200 HP Suzuki Twin Outboards, Gas, 4-Stroke Port Mdl# DF200AP, Port SN# 20003P-344571 Starboard Model# DF200AP, SN# 20003P-344568 Port Hours of Operation: 9 (Starboard & Port) Notes Hull has scratches and dings Many access panels are missing Vessel is taking on water from an unknown source Not equipped with a bimini or hardtop Fasteners missing where the deck is joined to the hull Twin outboards start/run Maximum rated HP for this vessel is 250 HP; There is currently 400 HP so the vessel may be overpowered per Chris-Craft specifications Above information derived from report dated September 2025"	Fulling, Robert [109]	$12,250.00
302	2004 Rolls Tandem Axle Trailer, VIN# 1R5DPLX2X41T14160, License Plate 07401778 " 1987 26' Mako 258 Cuddy Cabin and Trailer HIN# MRKS0361E787 Reg# Unknown Fiberglass Deep-V Hull PROPULSION: Yamaha 130 HP Gas, V-4, 2-Stroke, Saltwater Series Twin Outboards Port Mdl# 130TXRY, SN# 6L1X707183 Starboard Mdl# L130TXRY, SN# 6L6X702254 675 hours and 1775 hours Maintenance history unknown Outboards start and run No Generator NOTES: Vessel is in fair condition Scratches and dings throughout Bottom fiberglass is stained from years of being in saltwater with no bottom paint. Above information was derived from report dated June 2025"	Reingold, Leon [112]	$3,800.00
303	2004 21' Sea Pro Center Console (No Trailer), PIOJT593F404, Reg# FL 3186 MR 2024, Mdl Unknown, Fiberglass, Deep-V Hull, PROPULSION: Yamaha 200 HP Single Outboard, Outboard Mdl# F200TXR, SN# 1008099, No Generator Notes: This vessel is in fair condition; Outboard does not start. Above information was derived from report dated February 2025	Soler, Roniel [123]	$3,600.00
304	" 2003 21' Aquasport Center Console (No Trailer), HIN# AQABEA62B303 Reg# FL 6550 MH Fiberglass Deep-V Hull PROPULSION: Suzuki 200HP, 4-Stroke Outboard Mdl# DF200A, SN# 20003F-042508 No Generator NOTES: This vessel is in fair condition Hull has some scratches and the color is slightly faded Hull and topside gelcoat look good No top on the vessel One of the thru-hulls forward is leaking water Information above was derived from report dated May 2025"	Knafo, David [136]	$7,500.00
400	2021 Nautique Boat Paragon G25 US-CTC1R005E021 2020 Boatmate Trailer GT Tri, VIN# 5A7BB2533LT004781	Whitcomb, Mark [144]	$192,500.00

403	1999 23' Key West 2300 Walk Around "Blue Water", (No Trailer), HIN# KWEEW113J899, Reg# CF 3338 UH 2023, Fiberglass, Deep-V Hull, PROPULSION: 2004 Yamaha 200 HP 4-Stroke Single Engine Outboard, Gas, Mdl# F200TXRD, SN# 1004542, Hours: 816, Starts, Weak battery, Maintenance history unknown NOTES: Hull has scratches, dings and several gouges, Gelcoat on the sides of the vessel has scratches and gouges; Bottom antifouling paint is in poor shape; On the stern below the waterline there are holes where items have been removed and the repairs were poorly done; Upholstery is sun damaged; Bait tank was removed from the aft deck and the holes are still present; In the cockpit there are multiple holes where items have been removed and holes are not repaired; Aft seating has been removed and the holes are still present; Metals show signs of corrosion; Dash is sun damaged; Plastic rod holders in the stern are broken; Sink drain is corroded; Cowling is sun damaged. Above information was derived from report dated July 2025	Gomez Tagle, Cristian [146]	$5,000.00
601	" 1997 28' Bayliner Walkaround (No Trailer) HIN# USDA03FHK697 Reg# CF 9801 PD Fiberglass Modified-V Hull PROPULSION: 2012 350 HP Yamaha Single Outboard Engine, 4-Stroke SN# 1004558 NOTES: The lower unit is not original The skeg has a chunk out of it No keys to the outboard; Engine hours of operation and maintenance history are unknown The vessel looks like it was originally powered by twin outboards and has been repowered to just a single 350 HP Outboard engine Everything on the dash has been removed except for the fuel gauge There are 2 large holes in the dash where electronics have been removed The original twin controls are in place and have been modified down to a single control Down below is in fair shape Microwave has been removed Eisenglass enclosure is in fair shape Metals have light corrosion issues"	Vasek, Grant [96]	$2,300.00
603	"1999 39' HAWA Trawler (No Trailer) ""Silver Lining"" HIN# THH0405H99 Reg# CF 8923 ZJ Fiberglass Deep-V Hull PROPULSION: Lehman Twin Inboard Diesels, 4-cylinder No generator NOTES: HIN# is missing a character and not on the hull to be confirmed Wood topsides are bleached Hull is chalky and stained Bottom anti-fouling paint needs to be reapplied Interior in fair condition Wood flooring is worn and clear coating is damaged Engines do not start; Vessel is in overall fair condition needing work from lack of maintenance. Information above was derived from report dated March 2025"	Galis, Oscar [143]	$1,550.00
700	2005 28' Pursuit Offshore Center Console (No Trailer), HIN# SSUE8301C505, Fiber Reinforced Plastic (FRP), Notes: in dry dock, the bottom of the vessel was sounded with a phenolic hammer and all inspected areas were found to be in fair condition; Severe fracture and scratches were noted at the bow pulpit; Ample scratches at hull side bow, port side; Severe cracks at aft cleats bases and bait well frame; Moisture test was conducted with the G.E. Aquant Protimeter and all inspected areas were found to be in good condition. Above information was derived from report dated February 2025	Portell, Randall [98]	
	2005 225 HP Yamaha Engines F225TXRD, Serial Port# 69K-X-1006649-N, SN# Stbd# 69J-X-1018677-N		$26,000.00
701	(3) 75 HP Yamaha Gas Outboard Engines, Port SN# 6GJK-X-1013220, Stbd SN# 6GJK-X-1013219, 6GJK-X-1013086	Alcoba, Luis [23]	$7,250.00
703	9.9 HP Mariner Outboard Motor, SN# OC174294	Marrero, Juan [106]	$350.00
704	15 HP Mariner Outboard Motor, SN# 63V00 PH09	Lopez, Fernando [44]	$240.00