4/22/26 Specialty Auction			
Auction	**Description**	**Winner**	**Winning Bid**
100	"1966 Mooney M20C, N6007Q, Single Engine Airframe Total Time: 4507.9 est, Airframe Condition: Poor, Log Books: Airframe Only, MAINTENANCE STATUS: Maintenance Annual: 02/05/2019, Progressive Inspection: No, Aircraft is currently out of Annual, Service Bulletin Status: Unknown, Tires Condition: Good, Type Brakes: Fair, Anti-Skid: No, Exterior Paint Condition: White with a second color of blue stripes. Paint presently is in fair condition. Paint scheme is standard Mooney factory paint scheme for the 1960's. Interior Condition: Poor Cabin Configuration: Four Place: Pilot/Co-Pilot 2 Passengers Cockpit Condition: Poor Panel Layout: factory layout Pressurized Cabin: No Window Condition: Fair, Comments: The windows are all clear with some scratches and/or other blemishes. All instrument glass is clear but shows evidence of scratching to the sun glare coating. AIRFRAME MODIFICATIONS: N/A, DAMAGE HISTORY: No current damage, Historical Damage: N/A, ENGINES & PROPS: Engine Manufacturer: Lycoming Model: O-360-A1D, Engine Type: 100 Low Lead Fuel Engine Overhauled By: Unknown TBO:2400 Engine Fire Detection: No. Engine Fire Bottles: No. Time since Overhaul: Unknown Comments: No logbooks to determine and condition or times PROPELLER: Propeller Make: McCauley Number of Blades: Two Prop Reversers: No Prop Type: Variable Pitch Propeller TBO: 5 YRS OR 1500 HRS TSO/NEW: Unknown ENGINE MODIFICATIONS: None INSTRUMENTATION: Full Panel: Yes Dual Panel: no Panel Configurations: Standard Panel Condition: Poor IFR Equipped: YES AVIONICS: GPS is missing, Dual Controls: Yes Type: Yoke Stall Warning System: Yes. Stick Shaker: No. Rotating Beacon: Yes. Strobe Light: Yes. Taxi Lights: Yes. Navigation Lights: Yes. Long Range Fuel: No Aux Fuel Qty: 0 Single Point Refuel: No Toilet: No. Lavatory: No. Galley: No. Cabinetry: No; DE-ICING SYSTEMS: Known Ice System: No Ice Lights: No Prop De-Ice: No De-Ice Type: No Wing Tail Boots: No Boots Condition: N/A Windshield De-Ice: No Windshield Wipers: No Windshield: Pitot Heat: Yes Information above was derived from report dated September 2025"	McCarthy, David [1012]	$17,500.00
101	Saft Nickel-Cadmium Aircraft Delta Plus Battery (BTR), Cell Type: VHP230KA-3 for Airbus 321 Neo Airc	SWEITZER, DERRICK [1003]	$275.00
200	2018 Regal 35 Sport Coupe (No Trailer), HIN# RGMVH361J718, "Chrysanthemum"	Walker, Alan [97]	$142,500.00
300	2018 42' Yellowfin 42 Offshore with Tuna Tower (No Trailer), "Laid Tight", HIN# YFY42115H718, US Cert of Doc Official Number: 1285304, Fiber Reinforced Plastic (FRP), Deep-V Hull, PROPULSION: 4 Outboards, Mercury Racing , Gas, 450HP 450 HP, 4-Stroke Outboards Port: Mdl# 450R, SN# 14500072A, Starboard Center: Mdl# 450R, SN# 19500075A, Starboard Mdl# 450R, SN# 19500071A, NOTES: Vessel is in fair shape with no damage reported to the superstructure and hull; Anti-fouling bottom paint needs to be re-applied; In the compartment aft with the pumps, filter etc., the bronze thru-hulls are green from corrosion, rust stains from bleeding rust on the paint; Metal housing for the filters and pumps show signs of corrosion; (3) Three of the (4) four outboards start and run; Hours of operation and maintenance history are unknown	Kissoonlal, Jason [25]	$330,000.00
400	2002 31' Stamas 310 Express (No Trailer), HIN# STA31385C202, Reg# FL 4030 TG, Fiberglass, Deep-V Hull, PROPULSION: Suzuki 250 HP 4-Stroke, Twin Outboards, Gas , Outboard #1 Mdl/SN# DF250 SN# 25001Z 980022, Outboard#2: Model DF250 SN# 25001I 980069, NOTES: Vessel is in fair condition; Hull has some scratches, dings, and needs detailing. The bottom anti-fowling bottom paint is in fair condition with a few places that are worn through to the gelcoat; Cockpit upholstery is in fair shape; Topsides gelcoat needs detailing; There is a large hole in the dash from electronics that have been removed; Vessel is outfitted with a bow thruster that has not been tested; Outboards start and run; Hours of operation, model year, and maintenance history are unknown; Starboard outboard is missing the plastic mid-cowling cover; Total horsepower on this vessel is 500 and this vessel is at the maximum rated horsepower by the boat manufacture; Down below is stained and there appears to be holes in the wall coverings in several places. Flooring looks worn and in poor shape Above information was derived from report dated October 2025	Morales, Carlos [103]	$26,500.00

401	2003 25' Grady-White Voyager 258 Walkaround, (No Trailer), HIN# NTLVY435K203 , Reg# FL 8636KA, Fiberglass, Modified-V Hull, PROPULSION: 2002 Yamaha 225 HP, 4-Stroke Twin Outboards, Gas, Starboard Mdl# F225TXRA, SN# 002531, Port Outboard Additional Information: Pre-fix Model Code 69K Gear Box Shaft Length X Extra Long Shaft Starboard Outboard additional Info: Pre-fix Mdl Code 69J Gear Boc Shaft length X Extra Long Shaft NOTES: Hull has scratches, dings, and needs detailing; Bottom does not have antifouling bottom paint, and the gelcoat is stained. The pin-stripping and graphics are sun-damaged; Topsides need detailing; Upholstery is in fair condition; Aft cockpit seating needs repair; Outboards are in good condition and start/run; Hours of operation and maintenance history are unknown. The port outboard looks like it may be missing the last digit of the model LF225TXR?; Down below is in fair condition Above information was derived from report dated Sept. 2025	velez, victor [51]	$15,750.00
402	2003 27' Pro-Line 26 Walk-around (No Trailer), HIN# PLCWG011J203, Reg# FL 9681 LZ, Fiberglass, Deep-V Hill, PROPULSION: 2021 Suzuki 150 HP 4-Stroke Twin Outboards, Port Mdl# 15003F, Port SN# Z41889, Starboard Mdl# 15003F, Starboard SN# Z41892, Gas, No Generator, Notes: This vessel is in fair condition, Hull and topside gelcoat look good and the hardtop looks good; No damage reported; Cockpit deck is darker in color for unknown reason; The outboards are in fair condition and the start and run Above information was derived from report dated May 2025	Nikodinov, Nick [64]	$16,500.00
403	2001 22' Angler Center Console (No Trailer), w/ Suzuki 300HP OB Engine, HIN# ANGG0075I001, Reg# FL 8972 LK, Fiberglass, Deep-V Hull, PROPULSION: Suzuki , Mdl# DF300AP, Engine SN# 30002P 713663, Gas, 300HP, 4-Storke, No auxiliary, No generator NOTES: Vessel is in fair to good condition, Hull and topsides have some minor scratches; Outboard starts and runs, Hours of operation and maintenance history are unknown Information above was derived from report dated January 2026	Wohlfeld, Leydi [93]	$13,250.00
404	1987 25' Parker (No Trailer), HIN# PXM25422D787, Reg# GB 02970 (Bahamas), Fiberglass, Deep-V Hull, PROPULSION: Yamaha Single Outboard 300 HP, 4-Stroke, Gas, V-6 4.2L, Outboard Mdl# F300GET2, SN# 1021743, NOTES: Hull has multiple scratches and dings; Damage to portside at the rub-rail; Some damage to rub rail; There are areas where repairs have been done including the bow; Several areas where fittings are bleeding rust and gelcoat is stained; Bottom anti-fouling paint is in poor condition and needs to be reapplied; Cockpit needs detailing; Outboard starts and runs; hours of operation and maintenance are unknown Above information was derived from report dated August 2025	Rodriguez, Marcelino [38]	$12,250.00
405	1990 28' Wellcraft Coastal 2800, No Trailer, HIN# WELG0641G990, Reg# FL 2074 GX, Fiberglass, Modified-V Hull, PROPULSION: Yamaha 250 HP 2-Stroke Twin Outboards, Mdl/SN# unknown, No Generator. NOTES: This vessel is in fair condition considering it's age; The twin inboards were removed and replaced by twin outboards which this vessel was not designed for' Port outboard has heavy damage and the starboard runs but is in poor condition. Above information was derived from report dated February 2025	Soler, Roniel [6]	$225.00
500	2012 350 HP Yamaha Outboard Engine, Salt water cooling, SN# 1011691	torres, wilson [74]	
	350 HP Yamaha SN#1011687, V8 Four stroke out board Engine		$9,000.00
502	2001 Performance Trailers, 22' 6" Tandem Trailer, VIN# 402BA2000001, Plate: Arrastre 145133A, Manual winch, some corrosion, Poor condition	velez, victor [51]	
	2002 21' 9" (LOA) Cape Horn 210 Center Console "Lady Luna", HIN# FAB21089F102, Reg# PR 8644 GG, FRP, PROPULSION: 2008 115 HP Mercury 115XL 4S, Salt water cooling, Port SN# 1B556854, Starboard SN# 1B7237(XX-painted over) Notes: Vessel is in Fair Condition and is basically sound and in poor electrical condition, no other hidden damages were noted. Above information was derived from report dated January 2024		
	(2) 115 HP2008 115 HP Mercury 115XL, 4S, Salt water cooling, Port SN# 1B556854, Starboard SN# 1B7237(XX-painted over)		$12,000.00
504	40 HP Yamaha Outboard Engine, SN# 1191706	Crespo, Andres [54]	$850.00

600	2003 23' Wellcraft Coastal Tournament Edition WA (No Trailer), HIN# WELHKA06G203, Ger# CF 3360 KR 2025, Fiberglass, Deep-V Hull, PROPULSION: Volvo Penta Single Inboard Outboard, 5.0-I GXI Duo Prop, Gas I/O Model and Year Unknown, EN#: Unknown, Hours of Operation: Unknown, Auxiliary/Kicker: Yamaha 15HP, 4-Stroke, Year Unknown, Mdl# F15SEHA, SN# 1077335; NOTES: Vessel is in fair shape; Hull has normal wear and ear with scratches and the vinyl-stripes on the side are a little scratched up; Stern has several places where items were removed, and the screw holes were not properly repaired, there are several places where there are past repairs; Topsides in fair shape, Upholstery is sun damaged; Down below is dirty, Port-a-potty has been removed; The Volvo-Penta I/O started and ran in Oct. 2024 when the vessel arrived, Batteries are not chagrin enough at this time to start the engine; Mdl, maintenance history and hours of operation are unknown; Auxiliary Yamaha outboard or "Kicker" starts and runs, History of maintenance and year of manufacture are unknown 15 HP Yamaha Outboard Engine	Skelton, Dennis [59]	$1,950.00
601	2004 20' Triumph Center Console (No Trailer), HIN# US-TRBFA188L304	Nguyen, Christopher [55]	$2,300.00
603	"1988 25' Hydra-Sport Walkaround (No Trailer), HIN# HSX94725E888, Reg# CF 4537 UC 2025, Fiberglass, Deep-V Hull, PROPULSION: 2005 Evinrude Outboard, 225 HP, Gas, Mdl# E225DPXSOC, SN# 05101429, Hours of Operation: 0274.8 (not reliable), NOTES: exact model of this vessel is unknown; Vessel is in poor condition but no damage is reported, just years of the lack of maintenance, wear and tear; Hull has scratches and dings; Hull and topside gelcoat need detailing; Antifouling bottom paint is in fair shape; Small section of the rub-rail is damaged; On the stern there is an outboard bracket that has been relocated but the old holes are still there and have been poorly repaired. Some of the fittings are bleeding rust; Trim tabs show signs of corrosion; Upholstery is sun-damaged; Hardtop is in fair condition with no signs of corrosion; Window frame shows signs of corrosion; Multiple places with holes drilled into the gelcoat where items have been removed and the holes are open or poorly repaired; Several areas of gelcoat have spider-cracking; Stainless-steel railing in the cockpit has multiple holes drilled in the sections; Wood around the entrance to the cabin, wood trim in general, and the wood hatch to the cabin are very dry, needs refinishing, and some of it is damaged or missing; Base for the portside helm seat is damaged; Outboard turns over but does not start; Hour reading is unreliable (0274.8); Dash gauge cluster is not original and is from a Proline vessel; Throttle/shifter is made by Evinrude; Trim/tilt is not working, Outboard is stuck in the up position so the cowling cannot be removed for inspection; Exterior of Outboard has some corrosion; Interior is in poor condition Above information was derived from report dated October 2025"	Skelton, Dennis [59]	$1,000.00
800	1994 28' Bayliner 2859 (No Trailer), HIN# BLBA91SCD494, Reg# CF 5302 SM 2025, Fiberglass, Modified-V Hull, PROPULSION: Volvo Penta Single Inboard/Outboard, Mdl# KDA44 EDC, SN# Unknown, Diesel, Duo-Prop Outdrive (Twin Props), No Generator, NOTES: Hull has scratches and dings, Gelcoat needs detailing; Bottom anti-fowling paint needs to be re-applied; Two of the swim platforms supports are broken; Topside and helm area, and down below are in fair condition, Engine starts but has cooling issues with the water pick-up being partially blocked; Outdrive is in rough shape; Maintenance history is unknown Above information was derived from report dated July 2025	Galis, Oscar [81]	$4,250.00